



Service Info



Over-running alternator pulley 535 0263 10

Visual differences

Manufacturers: Hyundai, Jaguar, Kia, Land Rover

Models:

Hyundai: Grand Santa Fe, Santa Fe II, Santa Fe III, ix 35

Jaguar: XF

Kia: Carnival III, Grand Carnival III, Sorento II, Sportage

Land Rover: Evoque

Engines: D4HA, D4HB, 224DT

Transmission:

Hyundai: only Automatic

Jaguar: all Transmission

Kia: only Automatic

Land Rover: all Transmission

Alternator:

Denso: 104210-1060, 104210-6310

Part no.: 535 0263 10



Figure 1: Previous design



Figure 2: New design

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 535 0263 10.

This Service Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the transition period, we may have mixed stocks of both types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

