



## Service Info



# Bucket tappets 420 0059 10

## Visual differences

Manufacturer: Chevrolet, Daewoo, Saab

**Models:**

**Chevrolet:** Aveo, Lova  
**Daewoo:** Espero, Lanos, Leganza, Nexia, Nubira  
**Saab:** 900 II, 9000

**Engines:**

**Chevrolet:** F16D3D, L95  
**Daewoo:** A15MF, A16DMS, X20SED, Z20L  
**Saab:** B258I, B308I

Part no.: 420 0059 10

For current listing refer to catalogue media



Photo: Left - hydraulic bucket tappets of the competitor,  
 Right - hydraulic bucket tappets from INA (part no. 420 0059 10)

In the engines listed, the vehicle manufacturers are installing hydraulic bucket tappets from INA and from a competitor. The technical specifications of the two products are identical, there are only minor visual differences (photo).

The hydraulic bucket tappets can always be interchanged without any problem. Simultaneous use of different designs is permissible.

Please observe the vehicle manufacturer specifications!

**You want more? We can help!**

Phone: +44 (0) 1432 264 264\*  
 Fax: +44 (0) 1432 375 760  
 hfd-info@schaeffler.com  
 www.schaeffler-aftermarket.co.uk

\* Calls from within the UK 08457 001100